

# TEST CASE 1: WELL CONDUCTOR CUTTING

## Allseas, Reposl Gyda, Norway

Decom Engineering provided a C1-24 for this topside conductor recovery campaign, including two offshore technicians. The work scope included non-grouted, 20" multistring conductors.



### PROJECT OVERVIEW

Material	X70 grade, no grout
Deployment Method	Topside processing (HPU)
Average Cut Time	1 hour
Blade	5 - 10 cuts per blade

### SOLUTION PROVIDED

#### Full Equipment and Service Solution

#### Additional Services

- Project management
- Technicians

#### Additional Equipment and Handling

- Full topside power pack